

E.Coli Monitoring

For the past five years, samples have been taken from the perimeter of both the upper and lower lakes and tested for E.Coli using the official "beach monitoring" method. Values above 300 are of concern. Results continue to be very acceptable. Data is shown below.

Blub Blub Blurb: Fall 2008

	July 21, 2004	Aug. 3, 2005	Aug. 18, 2006	Aug. 15, 2007	Aug. 5, 2008
Collection Site	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml
Narrows	1	0	57	1	2
Dunes North	2	0	37	1	16
Dunes Middle	0	1	10	0	1
Dunes South	3	3	2	0	9
Entrance to State Park	0	0	0	0	0
Piney Ridge North	0	1	0	3	1
Piney Ridge South	1	0	0	0	0
Tamarac	2	3	5	12	10
South Bayou	2	1	33	8	9
Middle Bayou	7	0	12	3	10
Shoreline North of Middle Bayou	0	0	0	0	1
North Bayou	2	0	24	0	4
Partridge Point Swimming Area	0	3	13	0	2
Lower Lake--East of Deep Basin	3	0	0	1	2
Sunset Bay	1	0	27	1	1
Outlet to Indian Pete	0	0	0	1	4
Outlet to east arm of Indian Pete	15	2	214	4	5
Barnhardt's Marina	0	0	2	0	9
Wilson Hill Park	0	4	0	0	3
Layman's landing	0	26	0	4	1
Victory Park	1	36	370	6	4
Upper Reaches, Near swans	68	8	4	57	19