

Great Lakes Water Quality Laboratory, Inc.
P.O. Box 131
Lake Ann, MI 49650

Hamlin Lake		231-275-7382					
Results Report							
		July 28, 2009	August 5, 2008	August 15, 2007	August 18, 2006	August 3, 2005	July 21, 2004
NO	Collection Site	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml	E.coli/100 ml
1	Narrows	1	2	1.0	57	0	1
2	Dunes North	11	16	1.0	37	0	2
3	Dunes Middle	41	1	0.0	10	1	0
4	Dunes South	8.6	8.6	0	2	3	3
5	Entrance to State Park	0	<1	0	0	0	0
6	Piney Ridge North	0	1	3.1	0	1	0
7	Piney Ridge South	0	<1	0	0	0	1
8	Tamarac	7.4	9.9	12.0	5	3	2
9	South Bayou	15.8	8.6	7.5	33	1	2
10	Middle Bayou	4.1	9.8	3.0	12	0	7
11	North of Halls Shoreline	3.1	1	0	0	0	0
12	North Bayou	2	4.1	0	24	0	2
13	Partridge Point swimming area	7.5	2	0	13	3	0
14	Lower Lake--east of deep hole	5.2	2	1.0	0	0	3
15	Sunset Bay	0	1	1.0	27	0	1
16	Outlet to Indian Pete	0	4.1	1.0	0	0	0
17	Indian Pete--Outlet to east bayou	0	5.2	4.1	214	2	15
18	Barnhardts	1	8.6	0	2	0	0
19	Wilson Hill	1	3.1	0	0	4	0
20	Layman's landing	2	1	4.1	0	26	0
21	Victory Park	1	4.1	6.3	370	36	1
22	Upper Reaches, Near swans	10.9	18.9	57.3	4	8	68
23	Malliet Bayou	3.1	6.3	2.0	0	8	0
24	North Shore-East of Babcock	3.1	1	0	1	0	0
25	Rupert Bayou--Gartside	0	1	0	0	10	0